

High Vibrations during operations

- Causes nuts & bolts to loose
- Creating a need to Re-Torque.

But there is no visual indication of a loose nut, so you have to Re-Torque each one of them.

Checkpoint Indicator's;

- An intelligent solution
- Enabling Quick Visual Checks
- Higher Productivity
- Enhanced Safety










Dustite

Dustite LR



For more Information Contact Us:

Email: sales@tyrexperts.com Call/WhatsApp: 9136604919



