## High Vibrations during operations

- Causes nuts & bolts to loose
- Creating a need to Re-Torque.

But there is no visual indication of a loose nut, so you have to Re-Torque each one of them.

## **Checkpoint Indicator's;**

- An intelligent solution
- Enabling Quick Visual Checks
- Higher Productivity
- Enhanced Safety

OUR RANGE









Protect from Mud & Dust with Dustite/LR (\*Check with us sizes available)



For more Information: www.checkpointsafety.com

Email: sales@tyrexperts.com // surya@tyrexperts.com

Call: 9136604919//9874545500//9920841571// 02227562892

